

SEAL REPLACEMENT/ FITTING KITS

FRONT MOUNT CYLINDER


Part # HC5345, HC5347, HC5348, HC5358

NOTICE

Bleeder Fitting (Item #4)
is available in Fitting Kit
#HF5548

NOTICE

Replacement Tiller
Washer Assembly
available in Kit #HA5820



* PARTS INCLUDED IN HS5157

| ITEM | PART# | QTY | DESCRIPTION |
|------|--------|-----|--------------------------------|
| 1 | 797021 | 2 | Seal Gland Only |
| 2 | 745920 | 1 | Seal Gland Assembly Guide Tool |
| 3 | 745525 | 1 | Pin Wrench Only |
| 4 | 828980 | 2 | Bleeder Fitting |
| 5 | 600620 | 2 | Elbow Fitting |

| SEAL KIT # HS5157 | | | |
|-------------------|--------|---|--------------------------------|
| 1 | 797021 | 2 | Seal Gland Only |
| 2 | 745920 | 1 | Seal Gland Assembly Guide Tool |
| 3 | 745525 | 1 | Pin Wrench Only |

| TILLER BUSHING KIT # HA5820 | | | |
|-----------------------------|--------|---|-----------------------|
| 6 | 739123 | 1 | Washer, Bush, SS |
| 7 | 922221 | 1 | Washer, Snap, SS |
| 8 | 828010 | 1 | Bush, Tiller, Nylon |
| 9 | 890968 | 2 | Washer, Nylon |
| 10 | 113225 | 1 | HHCS 3/8UNJFX1.35 HSS |
| 11 | 113529 | 1 | Nut, Nylok® |

| FITTING KIT # HF5548 | | | |
|----------------------|--------|---|-----------------|
| 4 | 828980 | 2 | Bleeder Fitting |